

# Wasting precious Machining Time during Tool Set-Up change?


.....We can help.....

## MECHMATRIX offers the EASYMECH Range of CNC Machining Centre Accessories.

- > Z Axis Height Presetting Gauge
- > Tool Setting Fixture
- > Electronic Touch Point Sensor
- > Mechanical Edge Finder
- > Pull Studs
- > Milling Vice Hydraulic


### Z Axil Height Gauge

TYPE	HEIGHT	G.W.WEIGH T KGS	LxWxH/ UNIT:mm	Magnetis m
NZH-50A	50.00+-0.005mm	1.3 Kgs	50x63x63	O
NZH-50B	50.00+-0.005mm	1.3 Kgs	50x63x63	X



### ZOP-50

TYPE	HEIGHT	Net Wgt/Kgs	LxWxH/ UNIT:mm	Bottom have magnetic	Remark
NZH-50A	50.00+-0.005mm	1.3 Kgs	50x63x63	O	Machine needs conductive before use
NZH-50B	50.00+-0.005mm	1.3 Kgs	50x63x63	O	Machine is not conductive can also be used




## OPTICAL FINDER



MODEL	G.W.WEIGHT KGS	ACCURACY	LxWxProbe head/ UNIT:mm
OP-20	0.20	+0.005	158x20x10
OP-20BB	0.20	+0.005	158x20x10
OP-32	0.20	+0.005	158x32x10
OP-32BB	0.20	+0.005	158x32x10

## MECHANICAL EDGE FINDER



MODEL	G.W.WEIGHT KGS	ACCURACY	LxWxProbe head/ UNIT:mm
ME-610	0.80	+0.005	65x10x10
ME-420	0.14	+0.005	86x20x10
ME-1020	0.12	+0.005	83x20x10
WH-1020 (CERAMIC)	0.052	+0.005	83x20x10
WH-1020A (CERAMIC)	0.052	+0.005	86x20x10
WH-1010	0.036	+0.005	86x10x10